

Architectural Photographs



Photo No. 1– Disabled parking space: Note the missing wheel stop and missing “NO PARKING” text in the loading area. Also, the vertical clearance does not comply with ADA requirements.



Photo No. 2– Vehicle Barrier: The existing pipe railing cannot withstand a 6000 lb load per 2007 CBC requirements.



Photo No. 3– Typical Signage: Restroom signage is missing female pictogram (top). Text for stair signage does not comply with 2007 CBC requirements (middle). Stair signage inside the stairwell complies with 2007 CBC requirements (bottom).





Photo No. 4– Stair 2: This photo shows the door from the corridor on the right and the door to the exit passageway on the left. Stair 2 is acting as an intervening room between the corridor and the exit passageway.



Photo No. 5– Stair 2: View inside the exit passageway from Stair 2.



Photo No. 6– Breathing Air Tanks Inside Stair 2: View of existing breathing air tanks located beneath the metal stairs. The pipeline from the tanks runs to the adjacent fire control room.



Photo No. 7– Main Lobby: View of the recessed planters which create a drop-off hazard.



Photo No. 8— Examples of Water Intrusion: View of a water stained ceiling panel beneath a VAV box (top). Close-up view of a water stained light fixture lens (middle). View of an “All-Wik” at a window sill (bottom).

