

KEYED SHEET NOTES

①

GENERAL NOTES

- ① LCD INSPECTION LOCATIONS ARE APPROXIMATE.
- ② THE LOCATION OF VAVS (TERMINAL UNITS) IS APPROXIMATE.

LEGEND

- ACTIVE WATER LEAK
- CURRENT WATER STAINED SURFACE
- HISTORIC WATER LEAK/STAINED SURFACE
- CURRENT MOLD GROWTH
- HISTORIC MOLD GROWTH
- CURRENT WATER ON FLOOR
- HISTORIC WATER ON FLOOR
- DESTRUCTIVE TESTING LOCATION (HISTORIC)
- 325 ROOM NUMBER
- LCD INSP. LOCATION NO FINDINGS
- LCD INSP. LOCATION ACTIVE LEAK
- LCD INSP. LOCATION WATER STAIN
- LCD INSP. LOCATION OTHER NOTATION SEE WDA SUMM.
- LCD INSP. LOCATION WITH MULTIPLE FINDINGS "A", "B", OR "C" AS INDICATED



PRIME CONSULTANT



REVISIONS

NO.	DATE	NOTES
11/23/08		DRAFT
12/14/08		FIELD EDITS
12/17/08		FIELD EDITS
2/3/09		FIELD EDITS
2/11/09		FIELD EDITS
2/21/09		FINAL EDITS
2/25/09		FINAL EDITS

CLIENT
 STATE OF CALIFORNIA
 DEPARTMENT OF GENERAL SERVICES
 (DGS NO. 125828)
 (AGMT. NO. 3126150)

PROJECT LOCATION
 BOARD OF EQUALIZATION BUILDING
 450 N STREET
 SACRAMENTO, CA. 95814

PROJECT DESCRIPTION
 STATE OF CALIFORNIA, DGS
 BOE ASSESSMENT
 (LCD NO. 2372-572)

DESCRIPTION
 WATER DAMAGE
 SURVEY

LOCATION
 21ST FLOOR

SHT NO. 21
 SHT NAME A21