




- 1) Image within tenant occupied hallway working space of 20th floor adjacent to 2014 Break Room Area at time of assessment.



- 2) Image of Break Room 2014 pressure data logging equipment as viewed from occupied hallway at time of clearance assessment.



3) Image of exterior containment structures and postings at entrance to Break Room 707 area at time of assessment.



4) Image of exposed wall cavity, exposed plumbing, removed floor tile, and delineation of wallboard removal within Break Room 2014 at time of assessment.



5) Image of interior containment entry chamber and flex exhaust HEPA ducting within Break Room 2014 at time of assessment.



6) Image of air sampling equipment and critical barrier over existing tenant postings within break room 2014 area at time of assessment.



7) Close up image of exposed plumbing and metal floor sill framing following mitigative cleaning as viewed within Break Room 2014 at time of assessment.



8) Image of exposed metal wall framing where HTI technician (Larry) collects surface tape lift sample at time of assessment.



9) Close-up image of HTI technician collecting surface sample on exposed concrete surface within break room 2014 at time of assessment.



10) Image within break room 2014 containment viewing ceiling and wall posting barrier plastic maintained by JLS for duration of mitigative effort.