

KEYED SHEET NOTES


- 1 N/22 AND M/18.5 HIST. WS ON SHEETROCK CLG MEMBRANE ABOVE T-BAR.
- 2 WS IN LIGHT FIXTURE (CURRENT)
- 3 WS ON C.T. (CURRENT)
- 4 WS ON PUNCHOUT WINDOW (CURRENT)
- 5 WATER DAMAGE AT WINDOW
- 6 VMG IN BREAKROOM-SEALED.
- 7 WATER DAMAGE AT COLUMN
- 8 DAMAGE PAINT. AT PUNCH OUT WINDOW

GENERAL NOTES

- 1 THIS FLOOR HAS A SHEET ROCK CEILING MEMBRANE ABOVE THE T-BAR CLG ATTACHED TO THE UNDERSIDE OF THE STRUCTURAL DECK FOR SOUND PROOFING.
- 2 SEE LOCATION AND SAMPLING SUMM. FOR LD DESTRUCTIVE TESTING LOCATIONS
- 3 THE LOCATION OF VAV'S (TERMINAL UNITS) IS APPROXIMATE

LEGEND

- CURRENT WATER STAINED SURFACE
- CURRENT MOLD GROWTH
- HISTORIC MOLD GROWTH
- HISTORIC WATER LEAK/ STAINED CEILING TILE
- ACTIVE WATER LEAK
- CURRENT WATER ON FLOOR
- HISTORIC WATER ON FLOOR
- DESTRUCTIVE TESTING LOCATION (HISTORIC)
- 325 ROOM NUMBER
- LCD INSP. LOCATION NO FINDINGS
- LCD INSP. LOCATION ACTIVE LEAK
- LCD INSP. LOCATION WATER STAIN
- LCD INSP. LOCATION OTHER NOTATION SEE WDA SUMM.
- LCD INSP. LOCATION WITH MULTIPLE FINDINGS "A", "B", OR "C" AS INDICATED



PRIME CONSULTANT



REVISIONS

NO.	DATE	NOTES
11/23/08	DRAFT	
12/14/08	FIELD EDITS	
12/17/08	FIELD EDITS	

CLIENT
STATE OF CALIFORNIA
DEPARTMENT OF GENERAL SERVICES

PROJECT LOCATION
BOARD OF EQUALIZATION
450 N STREET
SACRAMENTO, CA. 95814

PROJECT
STATE OF CALIFORNIA, DGS
BOE ASSESSMENT

DESCRIPTION
WATER DAMAGE SURVEY

LOCATION
11TH FLOOR

SHT NO. 12
SHT NAME A11