



REVISIONS

NO.	DATE	NOTES
1	11/23/08	DRAFT
2	12/14/08	FIELD EDITS
3	12/17/08	FIELD EDITS

CLIENT
STATE OF CALIFORNIA
DEPARTMENT OF GENERAL SERVICES

PROJECT LOCATION
BOARD OF EQUALIZATION
450 N STREET
SACRAMENTO, CA. 95814

PROJECT
STATE OF CALIFORNIA, DGS
BOE ASSESSMENT

DESCRIPTION
WATER DAMAGE
SURVEY

LOCATION
1ST FLOOR

SHT NO. SHT NAME
2 A1

KEYED SHEET NOTES

- ① L/19 WEeping PIPES WITH WS ON WALLS AND CLGS.
- ② N.5/20 CITY STORM DRAIN CAUSE OF WATER DAMAGE
- ③ L/18.6 FIRE SPRINKLER RISER VMG
- ④ J LINE. WATER DAMAGE FROM PARKING GARAGE TO BUILDING FLASHING PROBLEM.
- ⑤



GENERAL NOTES

- ① THIS SHEET IS IN 16TH SCALE. ACCORDINGLY, THE SYMBOLS ARE NOT IN PROPORTION.
- ② FOR LCD DESTRUCTIVE TESTING LOCATIONS, SEE LOCATION AND SAMPLE SUMMARY.

LEGEND

- CURRENT WATER STAINED SURFACE
- CURRENT MOLD GROWTH
- HISTORIC MOLD GROWTH
- HISTORIC WATER LEAK/ STAINED CEILING TILE
- ACTIVE WATER LEAK
- CURRENT WATER ON FLOOR
- HISTORIC WATER ON FLOOR
- DESTRUCTIVE TESTING LOCATION (HISTORIC)
- 325 ROOM NUMBER
- LCD INSP. LOCATION NO FINDINGS
- LCD INSP. LOCATION ACTIVE LEAK
- LCD INSP. LOCATION WATER STAIN
- LCD INSP. LOCATION OTHER NOTATION SEE WDA SUMM.
- LCD INSP. LOCATION WITH MULTIPLE FINDINGS "A", "B" OR "C" AS INDICATED

THE GROUND FLOOR PLAN IS REDUCED. SCALE 1"=16'



ELEVATOR CORE ENLARGEMENT

