

**KEYED SHEET NOTES**


- ① RUSTY VALVE, WS
- ② STANDING WATER ON FLOOR
- ③ WS ON PUNCH PUT WINDOW
- ④

**GENERAL NOTES**

- ① FOR LCD DESTRUCTIVE TESTING LOCATIONS, SEE LOCATION AND SAMPLE SUMMARY.
- ② THE LOCATION OF VAV'S (TERMINAL UNITS) IS APPROXIMATE

**LEGEND**

- CURRENT WATER STAINED SURFACE
- CURRENT MOLD GROWTH
- HISTORIC MOLD GROWTH
- HISTORIC WATER LEAK/ STAINED CEILING TILE
- ACTIVE WATER LEAK
- CURRENT WATER ON FLOOR
- HISTORIC WATER ON FLOOR
- DESTRUCTIVE TESTING LOCATION (HISTORIC)
- 325 ROOM NUMBER
- LCD INSP. LOCATION NO FINDINGS
- LCD INSP. LOCATION ACTIVE LEAK
- LCD INSP. LOCATION WATER STAIN
- LCD INSP. LOCATION OTHER NOTATION SEE WDA SUMM.
- LCD INSP. LOCATION WITH MULTIPLE FINDINGS "A", "B", OR "C" AS INDICATED



PRIME CONSULTANT



REVISIONS

NO.	DATE	NOTES
11/23/08	DRAFT	
12/14/08	FIELD EDITS	
12/17/08	FIELD EDITS	

CLIENT  
STATE OF CALIFORNIA  
DEPARTMENT OF GENERAL SERVICES

PROJECT LOCATION  
BOARD OF EQUALIZATION  
450 N STREET  
SACRAMENTO, CA. 95814

PROJECT  
STATE OF CALIFORNIA, DGS  
BOE ASSESSMENT

DESCRIPTION  
WATER DAMAGE SURVEY

LOCATION  
7TH FLOOR

SHT NO. 8  
SHT NAME A7