



December 18, 2009

Mr. Michael Moore
California Department of General Services
Professional Services Branch
707 Third Street, 3rd Floor
W. Sacramento, CA 95605

Floor 11 Remediation Action Map
California State Board of Equalization
450 N Street
Sacramento, California


Dear Mike:

Please find a copy of the Floor 11 Remediation Action Map attached to the inside cover of the LCD Floor 11 Closure Report. This supplementary map is NOT a regular component of the Closure Reports that have been or will be developed for the BOE Mold Remediation Project. It was developed by the LCD field staff to document the following Remediation Actions associated with the gypsum board acoustic ceiling on Floor 11:

- Sections of "water-stained" gypsum board acoustic decking that were tested and removed due to the presence of visible mold growth (VMG);
- Sections of "water-stained" gypsum board acoustic decking that were tested and no VMG detected; marked with a colored coating to indicate that it had been tested and determined to be clean;
- Sections of "water-stained" fireproofing that were tested, removed, and replaced due to the presence of VMG;
- Sections of "water-stained" fireproofing that were tested and no VMG was detected; marked with a colored coating to indicate that it had been tested and determined to be clean.

Any questions related to this drawing may be directed to Mr. Ted Ice or Chris Corpuz at (925) 299-1140.

Yours very truly,
LaCroix Davis LLC


Chris Corpuz, MS, CIH
Senior Manager

