



APPENDIX B – INVESTIGATION PHOTOGRAPHS




Photo 1: Cracked spandrel glass near gold bull-nose attachment



Photo 2: Close-up view of the crack origins



Photo 3: The origin of the break is at a 90 ° angle from the edge



Photo 4: View of interior gasket out of place directly behind origin of crack



Photo 5: Damaged edge of glass