

Attachment A: Digital Images

June 11th, 2008

BOE Building 19th Floor Break Room Areas (1905 + 1908)
Sacramento, CA



- 1) Image of 19th Floor Break Room (1905) main entrance at time of assessment of BOE Building (Subject Building) located at 450 N Street, Sacramento, California.



- 2) Image of sink cabinet at time of assessment. Noted signage and interim plastic and duct tape barriers were present as noted as installed (according to DGS) by BPM site representatives.



3) Image of dark liquid staining present on tile flooring at cabinet door entry at time of assessment.



4) Close-up image of stained and cracked cabinet materials associated with chronic historic moisture release within sink area plumbing systems.



- 5) Image of sink cabinet “S” effluent trap and InstaHot water heater unit on rear wall. Note staining trail from InstaHot unit visible in image at time of assessment.



- 6) Image of entry to room 1908 which shares an interior wall and is adjacent to break room 1905.



- 7) Image of staired wall within 1908 which is immediately adjacent to the break room impacted cabinet materials. Baseboard and sheetrock materials indicated elevated moisture content at the time of assessment.