



- 1) Image of ambient air sampling location at front entry of BOE Building (Subject Building) located at 450 N Street, Sacramento, California at time of assessment.



- 2) Image of interior first floor reception area with conference rooms on right of picture. Barrier systems established at doorway at time of assessment.



3) Image of air sampling equipment utilized within interior of conference room 105 at time of assessment.



4) Image of representative ceiling barrier system (Room 105) utilized within each conference room as recommended by BioMax.



- 5) Image within 106 of concrete subflooring and perimeter metal framed supports present following carpet removal and detail cleaning.



- 6) Image within 106 of containment barriers and equipment in use at time of clearance assessment.




- 7) Image within 107 perimeter wall indicating residual stained concrete flooring at metal wall framing.



- 8) Additional close-up image of within 107 indicating condition of perimeter wall building materials following the performance of extensive clean up measures by JLS.



- 9) Image within conference room 110 where no mitigative carpet removal was performed. Air sampling for verification purposes only.



- 10) Image of air sampling equipment and location within conference room 111 at time of assessment.