

Attachment A: Digital Images

October 29th, 2008

BOE Building 5th and 6th Floor Storage Area Assessment
Sacramento, CA




- 1) Condition of Storage Room 6C wherein extensive quantities of cubicle furniture was stored creating limited access for inspection and sampling during assessment.



- 2) Image within Storage Room 6C of wall surface indicating suspect “smudges” which were sampled as part of surface assessment on 10/29/08.



- 3) Image within Storage Room 5C wherein wall-bolted metal framed shelving had covered localized suspect mold-like growth at lower shelf area.



- 4) Close-up image of stained wall surface following removal of office equipment from lower shelf at time of assessment.



- 5) Image of air sampling and wall debris present within Electrical and Telephone Equipment Room located at northeastern access doorway of 5th floor.



- 6) Close-up image of black “fuzzy” material present on southern wall within 5th Floor Electrical and Telephone Equipment Room.



7) Image of air sampling and storage materials present within storage room 5B at time of follow-up airborne and surface assessment performed on 11/05/08.



8) Image of stored material covering stained wallboard material within storage Room 5B at time of assessment.



9) Close image of stained material on wallboard surface within storage Room 5B at time of assessment.



10) Image of “sluffed” paint material present on wall-to-ceiling interface within Storage Room 5B at area above and adjacent to visible wall staining.