



- 1) Image of security area kiosk containment entry at time of clearance assessment of BOE Building (Subject Building) located at 450 N. Street, Sacramento, California.



- 2) Image of ambient air sampling location prior to the performance of interior containment assessment activities.




3) Image of air sampling activity performed at center area of Security Kiosk plenum area at time of assessment.



4) Image of air sampling activity performed at eastern side of Security Kiosk plenum area at time of assessment.




5) Image of ceiling structures and physical systems as viewed from Security Kiosk plenum area at time of assessment.



6) Image of plywood walk-on flooring present within Security Kiosk plenum area at time of assessment.



- 7) Close-up image of critical barrier isolating damaged materials (from Security Kiosk plenum area) located at southeastern most portion of plenum at time of assessment.



- 8) Image of air sampling performed within occupied elevator lobby area located adjacent to Security Kiosk area at the time of assessment.