SECTION 3

SECTION 4

SECTION 2

NORTH

NORTH QUADRANT CONTAINMENT

North Quadrant Containment

BioMax Containment

WEST Quadrant STAGING AREA

EAST QUADRANT CONTAINMENT

Quadrants Containment Barriers

Quadrant containment barrier

Quadrant Barrier

Hallway Containment Barriers

Hallway Containment Barrier

NW punch out containment

SW punchout containment

No issues

No issues

No issues

No issues

No issues

No issues

Moisture detected at Sample location respray FP on opposite side of wall

Total Dust 4
Fibers 4
MVOC (13) 2 SE, NW
Formaldehyde
CO_2
Rh
Temp
Mold (spore count) 8 + 2

= water stains FP/deck/GB
= PAINT on FP deck/overspray
= paint on FP beams or stains (tested no mold growth)
= removed FP on beams - BioMax containments only
= removed gyp wall board / removed gyp board ceiling and insulation (water stains on GB identified by BioMax)

(General Note* All Locations Approx) (Plan and locations may be altered by BioMax prior to LCD involvement)

Floor 11

BioMax Containment work completed prior to Quadrant work

North