APPENDIX C – FIGURES





Figure 1: Typical Thermal Break Pattern in Glass
(Taken from www.glassresource.com)



Figure 2: Elevation of Observed Cracking Pattern



Figure 3: Section Detail at Anchor Connection