

From: Executive Director
Sent: Thursday, April 10, 2008 5:03 PM
To: +All HQ Employees
Subject: Building Update - April 10, 2008

The Department of General Services has notified us that the source of the water intrusion on the first floor in the conference rooms is the sprinkler system, which has been turned off until the sprinklers can be relocated or permanently adjusted/changed to ensure they will not spray on the building in the future.

According to DGS, the water seems to have penetrated through the window mullions as a result of the sprinklers spraying directly on the window system. McGinnis Chin has been asked to assess the window system and provide a report.

We are awaiting the results of the air and surface testing from Hygiene Technologies and DGS' hygienist is also taking steps to assess, isolate and test the area to determine the next course of action.

I will continue to provide information to you as it becomes available.