

-----Original Message-----

From: Executive Director

Sent: Thu 5/15/2008 4:47 PM

To: +All HQ Employees

Subject: Building Update - May 15, 2008

Upon discovery of a water leak in break room 2014 on Tuesday, May 13, air and swab tests were taken by both our hygienist, Hygiene Tech and the DGS hygienist. According to the consultants, air data both within and surrounding room 2014 were "unremarkable". DGS' hygienist also reports bulk material samples confirmed the presence of mold growth as Penicillium/Aspergillus-type spores, which are indicative of chronic moisture damage conditions.

Based on these findings, DGS' consultant recommends that the break room remain closed and that current containment barriers remain in place until remediation work occurs.

A leaking refrigerator in break room 2008 is being replaced with a new one purchased by the employees who use the refrigerator. Tests taken in room 2008 were also found to be "unremarkable".

Employees may have noticed noises coming from the upper floors this week. DGS reports they are going to be moving modular furniture for the next couple of weeks, and that the noise will likely continue. DGS will also be doing containment and remediation over coming weeks, so other noises will likely arise. I appreciate your continued patience as we work through this process.