

From: Executive Director
Sent: Thursday, July 16, 2009 1:55 PM
To: +All HQ Employees
Subject: Building Update - July 16, 2009

DGS reports that a water leak has been discovered at the drinking fountain nearest the men's restroom on the 10th floor. Water has been cut off to the drinking fountain. DGS and its consultants have built a containment around the area in the hallway and have put it under negative air pressure. DGS reports they will immediately begin working on addressing the leak and the surrounding area. Our consultant, HTI, will monitor the work and conduct appropriate tests. We will keep you updated as information becomes available.