

**Table 2.1: Interview Summary**

Interviewed Personnel	Position at BOE	Time Worked at BOE	Responsibilities	Interview Date
Thomas Piette DGS	Supervising Architect	1998 - 2005	Roofing, perimeter integrity, water intrusions	9/23/2008
Jerry Piotrowski DGS	Chief Engineer II	1998 - 2005	Maintenance of all building systems	9/23/2008
Robert San Juan DGS	Chief Engineer II	2007 to date	Maintenance of all building systems	9/9/2008
John Munoz DGS	Office Building Manager II	2007 to date	Facility manager	9/9/2008
Dave Edwards DGS	Project Director	Feb. 1994 to date	Perimeter work related to building envelope (curtain wall and balconies)	9/9/2008
Rick Boggs JLS	Remediation Contractor/ Project Manager	Dec. 2007	Perform Fungal Remediation and Water Intrusion Cleanup	9/9/2008
Lance Lester DGS - ESHOP	Dept. Ind. Hyg. - BPM	1999 - 2007	Indoor air quality, investigation and remediation oversight	9/9/2008
Wes Frey HTI	IH Consultant (BOE)	Oct. 2007 to date	Indoor air quality, investigation and remediation oversight	8/7/2008
Ken Hsi HTI	IH Consultant (BOE)	Oct. 2007 to date	Indoor air quality, investigation and remediation oversight	8/7/2008
Brian Daly HTI	IH Consultant (BOE)	Oct. 2007 to date	Indoor air quality, investigation and remediation oversight	8/7/2008
Michael Polkabila BioMax	IH Consultant (DGS)	Nov. 2007 to date	Indoor air quality, investigation and remediation oversight	7/31/2008