



HYGIENETECH

Hygiene Technologies International, Inc.

3625 Del Amo Boulevard, Suite 180
Torrance, California 90503-1643
(310) 370-8370
(310) 370-7028 FAX
www.hygienetech.com

January 28, 2008

California State Board of Equalization
450 N Street
Sacramento, California 94279

Document No. 20801001.1

Attention: David Gau

Regarding: *Review of Recommended Mitigation Procedures for Floor 24*

Dear Mr. Gau:

On January 24, 2008, Hygiene Technologies International, Inc. (HygieneTech) received a copy of the "Recommended Mitigation Procedures for Floor 24" prepared by BioMax Environmental, LLC also dated January 24, 2008. Upon review of said document, HygieneTech has the following comments:

- 1) Wall cavity sampling on the 24th Floor, if necessary, will be collected this week. Such results will be provided to BioMax and other interested parties as soon as they are available.
- 2) A detailed visual inspection should be made of the ceiling plenum space and above all ceiling tiles throughout the entire floor to ensure that situations similar to that found in Room 2418 are not present elsewhere.

If you have any comments or questions, please feel free to contact our offices directly at (310) 370-8370.

Sincerely,

HYGIENE TECHNOLOGIES INTERNATIONAL, INC.

Kenny K. Hsi, CIH
Technical Director