

**Attachment A: Digital Images**

August 7<sup>th</sup>, 2008

BOE Building 22<sup>nd</sup> Floor North and West Containment Areas  
Sacramento, CA



- 1) Image of air sampling location (outside of containment) adjacent to occupied construction work space prior to containment sampling at time of assessment.



- 2) Image of air sampling location within 22<sup>nd</sup> Floor northern containment at BOE Building (Subject Building) located at 450 N Street, Sacramento, California at time of assessment.



- 3) Image of ambient air sampling performed within middle of the northern segment of 22<sup>nd</sup> Floor within the subject building.



- 4) Image of HTI technician (Makka) collecting surface sample within 22<sup>nd</sup> Floor northern containment area at time of assessment.



5) Image of air sampling location within 22<sup>nd</sup> Floor Northern containment area at northwestern corner of building.



6) Image of HTI technician collecting surface sample at window framing material within Northern containment area at time of assessment.



7) Image of air sampling equipment and location outside western containment area of 22<sup>nd</sup> Floor at time of assessment.



8) Image of air sampling apparatus utilized at perimeter corner wall within 22<sup>nd</sup> Floor western containment area at time of assessment.



9) Image of air sampling performed within office working space (2219) within western containment area.



10) Image of subflooring slab material with presence of filler material and some glue staining within southwestern corner area. Area adjacent to previously mold stained wall material.



11) Additional image of representative floor filler material used within western segment of containment area at time of assessment. Some area with glue on surface and some without.



12) Additional image of floor filler material within western containment area.



13) Image of air sampling equipment within 22<sup>nd</sup> Floor western containment area (Room 2221) at time of assessment.



14) Image of ambient air sampling equipment location on 23<sup>rd</sup> Floor northern balcony at time of assessment.



15) Image of air sampling equipment present within 22<sup>nd</sup> floor northern containment at northwestern punch out window area.