



- 1) Image of ambient air sampling location at front entry of BOE Building (Subject Building) located at 450 N Street, Sacramento, California at time of assessment.



- 2) Image of postings and alternate routing directions for BOE employees at hallway leading to break room containment on the 10<sup>th</sup> floor.



- 3) Image of cubicle work area located outside the established containment system where air sampling equipment is observed present in the foreground at time of assessment.



- 4) Image of hallway air sampling location adjacent to Break Room as viewed from 1014 cubicle area (outside containment) at time of assessment.



- 5) Image within 10<sup>th</sup> Floor break room containment 2424 containment indicating location of air sampling equipment and extent of removal of cabinetry and wallboard materials.



- 6) Additional image within Break Room containment area viewing corner where previous cabinetry had existed prior top removal.



- 7) Close-up image within Break Room containment showing plumbing detail and wall space cavity following physical removal of damaged materials.



- 8) Image of containment space located along north facing hallway adjacent to break room and office area.



9) Image of air sampling equipment location within office (1003) inside containment adjacent to break room at time of assessment.



10) Image within break room containment area showing establishment of ceiling barrier and negative air exhaust ducting onto hallway.