



- 1) Image of ambient air sampling location at front entry of BOE Building (Subject Building) located at 450 N Street, Sacramento, California at time of assessment.



- 2) Image of ambient air sampling location on 12th Floor southeast deck area at time of assessment.



3) Image of ambient air sampling location on 23rd floor western deck area at time of assessment.



4) Image of hallway air sampling location adjacent to Room 2424 containment (outside containment) at time of assessment.



- 5) Image within 2424 containment indicating location of air sampling equipment and removal of cabinetry and wallboard materials.



- 6) Image within 2424 containment viewing ceiling containment and exhaust ventilation at entry/exit chamber doorway.



- 7) Image within 2402 Break Room containment indicating location of air sampling equipment and physical cabinet and wallboard removal at time of clearance assessment.



- 8) Close-up image of location within 2402 containment where cabinetry and wallboard materials were removed by mitigation contractor.



9) Image of Hygientech (HTI) technician collecting surface tape sample at time of assessment within Break Room 2402 containment.



10) Image of Hygientech (HTI) technician collecting parallel spore trap air sample on 23rd Floor West Balcony following interior assessment.