



1



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 11 th floor; looking southeast and down; showing water staining	↑

2



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 11 th floor; looking east and down; showing water staining at fireproofing	↑



3



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 11 th floor; looking southeast and up; showing water staining	↑

4



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 11 th floor; looking southeast; showing water staining	↑



5



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 11 th floor; looking southwest and up; showing water staining	↑

6



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 11 th floor; looking southwest; showing water staining	↑



7



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 10 th floor; looking southwest and up; showing water staining	↑

8



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 10 th floor; looking south showing water staining	↑



9			
			
Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 10 th floor; looking southeast and up; showing water staining	↑

10			
			
Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 9 th floor; looking southwest; showing water staining	↑



11



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 9 th floor; looking southeast; showing water staining	↑

12



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 9 th floor; looking southeast and down; showing water staining at fireproofing	↑



13



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 9 th floor; looking east and down; showing water staining at fireproofing	↑

14



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 8 th floor; looking southwest and up; showing water staining	↑



15



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 8 th floor; looking southwest and down; showing water staining	↑

16



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 8 th floor; looking southeast and up; showing water staining	↑



17



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 8 th floor; looking southeast and down; showing water staining	↑

18



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 8 th floor; looking east and down; showing water staining	↑



19



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 8 th floor; looking southeast; showing water staining	↑

20



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 7 th floor; looking southwest and up; showing water staining	↑



21



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 7 th floor; looking southeast and down; showing water staining	↑

22



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 7 th floor; looking east and down; showing water staining	↑



23



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 6 th floor; looking southwest and down; showing water staining	↑

24



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 6 th floor; looking south and down; showing water staining	↑



25



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 5 th floor; looking southeast and up; showing water staining	↑

26



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 5 th floor; looking southeast and down; showing water staining	↑



27



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 5 th floor; looking southeast; showing water staining	↑

28



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 4 th floor; looking northwest and up; showing water staining	↑



29



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 4 th floor; looking southwest and up; showing water staining	↑

30



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 4 th floor; looking southwest and down; showing water staining	↑



31



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 3 rd floor; looking southwest and up; showing water staining	↑

32



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 3 rd floor; looking southwest and down; showing water staining	↑



33



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 3 rd floor; looking southwest; showing water staining	↑

34



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 3 rd floor; looking southeast and up; showing water staining	↑



35



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 3 rd floor; looking southeast and down; showing water staining	↑

36



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 3 rd floor; looking east and down; showing water staining	↑



37



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 3 rd floor; looking east and down; showing water staining	↑

38



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 2 nd floor; looking northwest and up; showing water staining	↑




39



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 2 nd floor; looking west and down; showing water staining	↑

40



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 2 nd floor; looking southwest and down; showing water staining	↑




41



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 2 nd floor; looking southeast and down; showing water staining	↑

42



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 1 st floor; looking northwest and up; showing water staining	↑



43



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 1 st floor; looking southwest and up; showing water staining	↑

44



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 2; 1 st floor; looking southwest and down; showing water staining	↑