



1



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 23 rd floor; looking north and down; showing suspect fungal growth	↑

2



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 22 nd floor; looking north and down; showing suspect fungal growth	↑



3



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Close-up of Photo 2	↑

4



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 21 st floor; looking northeast and down; showing suspect fungal growth	↑



5			
			
Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 20 th floor; looking north and down; showing water staining and suspect fungal growth	↑

6			
			
Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 20 th floor; looking northeast and down; showing suspect fungal growth	↑



7



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 13 th floor; looking northwest and up; showing water staining	↑

8



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 13 th floor; looking southwest and up; showing water staining	↑



9



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 11 th floor; looking west; showing water staining	↑

10



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 11 th floor; looking southwest; showing water staining	↑



11			
			
Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 11 th floor; looking southwest and up; showing water staining	↑

12			
			
Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 10 th floor; looking northwest and up; showing water staining	↑



13



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 10 th floor; looking northwest; showing water staining and suspect fungal growth	↑

14



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 9 th floor; looking northwest; showing water staining	↑



15



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 8 th floor; looking west; showing water staining	↑

16



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 8 th floor; looking northwest; showing water staining	↑



17



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 7 th floor; looking northwest and down; showing water staining	↑

18



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 6 th floor; looking northwest and up; showing water staining	↑




19



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 6 th floor; looking northwest and up; showing water staining	↑

20



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 5 th floor; looking southwest; showing water staining	↑



21



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 4 th floor; looking northwest and up; showing water staining	↑

22



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 4 th floor; looking west and up; showing water staining	↑



23



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 3 rd floor; looking northwest and up; showing water staining	↑

24



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 3 rd floor; looking north and down; showing water staining	↑



25



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 3 rd floor; looking north and down; showing water staining	↑

26



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 1 st floor; looking north and down; showing water staining	↑



27



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 5; 1 st floor; upper portion; looking north; showing water staining	↑