



1



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; Penthouse floor; looking south; showing suspect fungal growth	↑

2



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 24 <sup>th</sup> floor; looking east and up; showing water staining	↑



3



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 24 <sup>th</sup> floor; looking southeast and up; showing water staining	↑

4



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 24 <sup>th</sup> floor; looking northwest; showing water staining	↑



5



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 22 <sup>nd</sup> floor; looking southeast; showing suspect fungal growth	↑

6



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 22 <sup>nd</sup> floor; looking south; showing water staining and suspect fungal growth	↑



7			
			
Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 22 <sup>nd</sup> floor; looking southwest; showing suspect fungal growth and water staining	↑

8			
			
Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Close-up of Photo 7; showing suspect fungal growth on western partition wall	↑



9



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 20 <sup>th</sup> floor; looking west; showing suspect fungal growth	↑

10



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 19 <sup>th</sup> floor; looking west; showing suspect fungal growth	↑



11



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 18 <sup>th</sup> floor; looking west; showing suspect fungal growth	↑

12



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 17 <sup>th</sup> floor; looking southeast; showing suspect fungal growth	↑



13



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 17 <sup>th</sup> floor; looking south; showing suspect fungal growth	↑

14



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 17 <sup>th</sup> floor; looking south and down; showing suspect fungal growth	↑



15



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 16 <sup>th</sup> floor; looking southwest; showing suspect fungal growth	↑

16



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; M floor; looking east; showing water staining	↑



17



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; M floor; looking east; showing suspect fungal growth and water staining	↑

18



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 11th floor; looking east and up; showing water staining	↑



19



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 11 <sup>th</sup> floor; looking southeast; showing suspect fungal growth	↑

20



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 10 <sup>th</sup> floor; looking east; showing water staining	↑



21



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 10 <sup>th</sup> floor; looking southeast; showing suspect fungal growth and water staining	↑

22



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Close-up of Photo 21; showing suspect fungal growth	↑



23



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 9 <sup>th</sup> floor; looking east; showing water staining	↑

24



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 9 <sup>th</sup> floor; looking southeast; showing suspect fungal growth and water staining	↑



25



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 9 <sup>th</sup> floor; looking southeast; showing water staining	↑

26



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Close-up of Photo 25; showing suspect fungal growth and water staining	↑



27



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 8 <sup>th</sup> floor; looking northeast and up; showing water staining	↑

28



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 7 <sup>th</sup> floor; looking east and down; showing water staining	↑



29



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 7 <sup>th</sup> floor; looking east; showing water staining	↑

30



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 6 <sup>th</sup> floor; looking east; showing water staining	↑



31



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 6 <sup>th</sup> floor; looking northeast; showing water staining	↑

32



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 5 <sup>th</sup> floor; looking east and up; showing water staining	↑



33



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 5 <sup>th</sup> floor; looking east and up; showing water staining	↑

34



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 5 <sup>th</sup> floor; looking southeast and up; showing water staining	↑



35



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 4 <sup>th</sup> floor; looking east and up; showing water staining	↑

36



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 3 <sup>rd</sup> floor; looking east; showing water staining	↑



37



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 3 <sup>rd</sup> floor; looking northeast and up; showing water staining	↑

38



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 2 <sup>nd</sup> floor; looking northeast and up; showing water staining	↑



39



Date	Address	Photo Location – Description	Up
08/20/08	450 N Street Sacramento, California	Elevator Shaft 7; 2 <sup>nd</sup> floor; looking northeast; showing water staining	↑