



1



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 18 <sup>th</sup> Floor; looking west; showing suspect fungal growth and water staining	↑

2



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 14 <sup>th</sup> Floor; looking west and down; showing water staining	↑



3



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 14 <sup>th</sup> Floor; looking northwest; showing water staining	↑

4



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; M Floor; looking east; showing suspect fungal growth and water staining	↑




5



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; M Floor; looking east; showing suspect fungal growth and water staining	↑

6



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; M Floor; looking west and up; showing water staining	↑



7



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 11 <sup>th</sup> Floor; looking east; showing water staining	↑

8



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 11 <sup>th</sup> Floor; looking east; showing water staining	↑



9



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 10 <sup>th</sup> Floor; looking east and up; showing water staining	↑

10



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 9 <sup>th</sup> Floor; looking east and up; showing water staining	↑



11



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 8 <sup>th</sup> Floor; looking east; showing water staining	↑

12



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 5 <sup>th</sup> Floor; looking east; showing water staining	↑



13



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 4 <sup>th</sup> Floor; looking east; showing water staining	↑

14



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 3 <sup>rd</sup> Floor; looking east; showing water staining	↑



15



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 8; 2 <sup>nd</sup> Floor; looking east and down; showing water staining	↑