




1



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Elevator Shaft 10; above roof line; looking south; showing water staining at vent opening	↑

2



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Elevator Shaft 10; above roof line; looking west; showing water staining	↑



3



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Elevator Shaft 10; 3 rd floor; looking west and up; showing water staining	↑

4



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Elevator Shaft 10; 3 rd floor; looking northwest and up; showing water staining	↑



5			
			
Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Elevator Shaft 10; 2 nd floor; looking northwest and up; showing water staining	↑

6			
			
Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Elevator Shaft 10; 2 nd floor; looking northwest and up; showing water staining	↑



7



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Elevator Shaft 10; 2 nd floor; looking northwest; showing water staining	↑