



1



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 10 th floor; looking northeast and down; showing suspect fungal growth	↑

2



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Close-Up of Photo 1; showing suspect fungal growth on eastern partition wall	↑



3



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 5 th floor; looking east; showing water staining	↑

4



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 4 th floor; looking northwest and up; showing water staining	↑




5



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 4 th floor; looking west; showing water staining	↑

6



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 4 th floor; looking north; showing water staining	↑



7



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 4 th floor; looking north and up; showing water staining	↑

8



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 3 rd floor; looking southwest; showing water staining	↑



9



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 2 nd floor; looking southwest; showing water staining	↑

10



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 2 nd floor; looking west; showing water staining	↑




11



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 1 st floor; looking east and up; showing water staining	↑

12



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 1 st floor; looking east and up; showing water staining	↑



13



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator shaft 1; 1 st floor; looking northwest and up; showing water staining	↑