



1



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 10 th floor; looking southeast and up; showing water staining	↑

2



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 10 th floor; looking southeast; showing water staining	↑



3



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 5 th floor; looking east; showing water staining	↑

4



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 5 th floor; looking southeast and up; showing water staining	↑




5



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 5 th floor; looking southeast; showing water staining	↑

6



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft two; 4 th floor; looking east and up; showing water staining	↑



7			
			
Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 4 th floor; looking southeast; showing water staining	↑

8			
			
Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 4 th floor; looking southeast and up; showing water staining	↑



9



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 3 rd floor; looking southeast and up; showing water staining	↑

10



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 3 rd floor; looking southeast; showing water staining	↑



11



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 2 nd floor; looking southeast and up; showing water staining	↑

12



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 2 nd floor; looking southeast; showing water staining	↑



13



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 1 st floor; looking east and up; showing water staining	↑

14



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 1 st floor; looking southeast; showing water staining	↑



15



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; 1 st floor; looking southeast; showing water staining	↑

16



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; pit; looking southeast and up; showing water staining	↑



17



Date	Address	Photo Location – Description	Up
08/12/08	450 N Street Sacramento, California	Elevator Shaft 3; pit; looking southeast and up; showing water staining	↑