



1



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 24 th Floor; looking northeast and up; showing water staining	↑

2



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 23 rd Floor; looking north and up; showing suspect fungal growth	↑



3



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 23 rd Floor; looking northeast; showing water staining	↑

4



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 23 rd Floor; looking east; showing suspect fungal growth	↑



5



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 22 nd Floor; looking northeast and down; showing suspect fungal growth and water staining	↑

6



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 21 st Floor; looking east; showing suspect fungal growth and water staining	↑



7



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 21 st Floor; looking northeast; showing suspect fungal growth and water staining	↑

8



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 20 th Floor; looking northeast; showing suspect fungal growth and water staining	↑



9



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 20 th Floor; looking east and up; showing suspect fungal growth	↑

10



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 20 th Floor; looking east; showing suspect fungal growth	↑



11



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 20 th Floor; looking north and up; showing water staining	↑

12



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 19 th Floor; looking east; showing suspect fungal growth and water staining	↑




13



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 19 th Floor; looking northeast; showing suspect fungal growth and water staining	↑

14



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 19 th Floor; looking west and up; showing water staining	↑



15



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 18 th Floor; looking northeast; showing suspect fungal growth and water staining	↑

16



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 18 th Floor; looking west; showing suspect fungal growth and water staining	↑



17



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 17 th Floor; looking east and up; showing water staining	↑

18



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 17 th Floor; looking west; showing suspect fungal growth and water staining	↑



19



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 16 th Floor; looking east and down; showing suspect fungal growth and water staining	↑

20



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 16 th Floor; looking northwest and down; showing suspect fungal growth	↑



21



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 15 th Floor; looking west; showing suspect fungal growth and water staining	↑

22



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 14 th Floor; looking northwest and up; showing water staining	↑



23



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 14 th Floor; looking north; showing suspect fungal growth and water staining	↑

24



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; Maintenance Floor upper level; looking east and up; showing suspect fungal growth, water staining, and orange spray paint	↑



25



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; Maintenance Floor upper level; looking northwest and up; showing water staining	↑

26



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; Maintenance Floor lower level; looking east; showing suspect fungal growth	↑



27



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; Maintenance Floor lower level; looking east; showing suspect fungal growth, water staining, and the word “mold” in orange spray paint	↑

28



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 11 th Floor; looking north; showing suspect fungal growth	↑



29



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 11 th Floor; looking west; showing suspect fungal growth	↑

30



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 11 th Floor; looking east; showing water staining	↑



31



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 10 th Floor; looking northwest; showing suspect fungal growth and water staining	↑

32



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 10 th Floor; looking east; showing water staining	↑



33



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 9 th Floor; looking northwest and down; showing suspect fungal growth and water staining	↑

34



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 9 th Floor; looking north; showing suspect fungal growth and water staining	↑



35



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 8 th Floor; looking northwest; showing water staining; suspect fungal growth, and orange spray paint	↑

36



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 8 th Floor; looking east; showing water staining and suspect fungal growth;	↑



37



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 7 th Floor; looking north; showing suspect fungal growth	↑

38



Date	Address	Photo Location – Description	Up
08/18/08	450 N Street Sacramento, California	Elevator Shaft 9; 2 nd Floor; looking east and up; showing water staining	↑