




1



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; Penthouse; looking west; showing water staining	↑

2



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 21 st floor; looking southwest; showing water staining	↑



3



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight elevator shaft; 21 st floor; looking south; showing water staining	↑

4



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 19 th floor; looking southeast; showing rust staining	↑



5



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 18 th floor; looking northeast and up; showing light brown discoloration	↑

6



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 18 th floor; looking northeast and up; showing light brown discoloration	↑



7



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 17 th floor; looking east and up; showing light staining	↑

8



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 10 th floor; looking southwest; showing water staining	↑



9



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 9 th floor; looking southeast; showing water and rust staining	↑

10



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 8 th floor; looking southwest; showing water and rust staining	↑



11



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 8 th floor; looking southwest; showing water staining	↑

12



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 7 th floor; looking northwest and down; showing water staining	↑



13



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 6 th floor; looking north; showing suspect fungal growth	↑

14



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 4 th floor; looking northeast; showing water staining	↑



15



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 2 nd floor; looking south and up; showing water staining	↑

16



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 2 nd floor; looking northeast and up; showing water staining	↑



17



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 2 nd floor; looking northwest and up; showing water staining	↑

18



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 2 nd floor; looking west and down; showing water staining	↑



19



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 2 nd floor; looking south and down; showing water staining	↑

20



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 1 st floor; looking southwest; showing water and rust staining	↑



21



Date	Address	Photo Location – Description	Up
08/11/08	450 N Street Sacramento, California	Freight Elevator Shaft; 1 st floor; looking south and up; showing water staining	↑