Rosenberg McGinnis, AIA, Inc.

Capitol Square
Water Infiltration Investigation
Sacramento, California

Project Number 97187
1 June 1998

Capitol Square

450 N Street, Sacramento, CA

Water Infiltration Investigation #97187

1 June 1998



PREPARED FOR

McDonough, Holland & Allen
555 Capitol Mall, Suite 950
Sacramento, CA 95814
(916) 444-3900

PREPARED BY

Rosenberg McGinnis AIA, Inc.
2540 Pacific Avenue, Suite 8
Stockton, CA 95204
(209) 939-3399

TABLE OF CONTENTS

EXECUTIVE SUMMARY 3
INTRODUCTION 5
PROJECT DESCRIPTION 6
INVESTIGATION AND EVALUATION
- Curtainwall Glazing System 7
- Storefront 10
- Precast Concrete Panels 11
- Precast Concrete Column Covers & Louvers 12
- Building Expansion Joint 13
- Garage Elevator Penthouse 13
- Parking Garage Floor Slab 14
- Garage Stairwell Penthouse 15
- Mechanical Floor Corner Planters 15
- Third Floor Roof Decks 16
- Twenty Third Floor Terraces 16
- Roof Penthouse 18
- Helipad 20
- Other Issues 20

RECOMMENDATIONS
- Curtainwall Glazing System 21
- Storefront 21
- Precast Concrete Panels 22
- Precast Concrete Column Covers & Louvers 22
- Building Expansion Joint 22
- Garage Elevator Penthouse 23
- Parking Garage Floor Slab 23
- Garage Stairwell Penthouse 23
- Mechanical Floor Corner Planters 23
- Third Floor Roof Decks 23
- Twenty Third Floor Terraces 24
- Roof Penthouse 24
- Helipad 25

APPENDIX A - DRAWINGS
- Floor Plans
- Typical Curtainwall Partial Elevation and Wall Section SK0
- Details SK1 to SK10

APPENDIX B - LEAK INVESTIGATION SUMMARY
- Reported Leaks
- Investigation Schedule
- Watertest Summary

APPENDIX C - PHOTOGRAPHS
- Photograph Index
- Photographs 1 to 47